



REPLACEMENT FOR

OUTLANDER '05

REPLACEMENT FOR

PAJERO MONTERO '83-'91 4G54 LO47 V30

214-1179-LD-E

HEAD LAMP

R
L 8301A173
PCS CFT



HB3/H1/WY21W/W5W

TBA

214-1203-1

LIGHT CASE

R MB 283932
L MB 283931
10PCS 2.47CFT



214-2802

F/SIDE BUMPER

R MB 369554
L MB 369553
20PCS 2.5CFT



214-1992-UE2

TAIL LAMP

R
L 8330A049
PCS CFT



W5W/WY21W/WY21W/W21W/W16W

TBA

214-1203-2

LIGHT CASE

R MB 283576
L MB 283575
10PCS 2.47CFT



214-2803

F/SIDE BUMPER

R MB 369582
L MB 369581
10PCS 1.5CFT



'85-'91

214-1507

CORNER LAMP

R MB 283670
L MB 283669
20PCS 2.18CFT
00-214-1507 LENS
100PCS 3.36CFT



214-1922

TAIL LAMP

R MB 283722
L MB 283721
20PCS 4.45CFT
00-214-1922 LENS
100PCS 2.75CFT



214-2801

SIDE BUMPER

R MB 369552
L MB 369551
10PCS 1.4CFT



MITSUBISHI



REPLACEMENT FOR


PAJERO MONTERO '92-'94 V32 V34 SJ45 4G54 '92

214-1120-RD-E 43T
LD-E
HEAD LAMP
RD:
R MB 831068
L MB 831067
LD:
R MB 831066
L MB 831065
6PCS 4.74CFT



H4

214-1215-2 1
3
LIGHT CADE
2:
R MB 831056
L MB 831055
3:
R MB 831058
L MB 831057
5PCS 1.4CFT



214-2809-6 BASE
F/SIDE BUMPER
R MB 831048
L MB 831047
5PCS 3.87CFT



214-1531-AE
UE
CORNER LAMP
R MB 831082
L MB 831081
20PCS 2.8CFT



P21W/W5W

214-1530-A
CORNER LAMP
R MB 831080
L MB 831079
R MR 124956
L MR124955
20PCS 4.53CFT




P21W/W5W

214-2810
FRONT SIDE BUMPER
R MB 831050
L MB 831049
10PCS 6.53CFT



214-1938-1
TAIL LAMP
R MB 831490
L MB 831489
10PCS 4.7CFT



214-1938-2
TAIL LAMP
R MB 831086
L MB 831085
10PCS 4.7CFT



214-2808-6 RS.LS.SR
R/SIDE BUMPER
R MB 831720
L MB 831719
5PCS 2.38CFT



214-1415-C
SIDE LAMP
200PCS 2.85CFT



214-1938-N
TAIL LAMP
R
L
10PCS 4.7CFT



214-2808-2 BASE
REAR SIDE BUMPER
R MB 831054
L MB 831053
5PCS 2.38CFT



214-1415
SIDE LAMP
MB 831091
200PCS 2.85CFT



214-1946-UE
TAIL LAMP
R MR 124964
L MR 124963
20PCS 2.12CFT



P21W/P21/5W

Toutes les pièces énumérées dans ce catalogue ne sont pas originaux. Alle die in diesem Katalog abgebildeten Artikel, sind nicht original Teile. All items shown in this catalogue are not original parts. Todos los productos de este catalogo no son originales. Tutti i particolari raffigurati in questo catalogo non sono originali.



REPLACEMENT FOR

PAJERO MONTERO '98 V33

REPLACEMENT FOR

PAJERO MONTERO '00

214-1146-LD-E

HEAD LAMP
R MR 387534
L MR 387533
6PCS
4.82CFT



H4

214-1938-2AD

BLACK

TAIL LAMP
R
L
10PCS 6.01CFT



214-1159-LD-E2 LDEM2

HEAD LAMP
R MR 548036
L MR 548035
PCS CFT
R MR548034
L MR548033



H4/W21W/W5W

TBA

214-1556-AE

CORNER LAMP
R
L MR 387543
20PCS
4.47CFT



PY21/W5W

214-1938-1ADCR

CHROMED

TAIL LAMP
R
L
10PCS 6.01CFT



214-2026-AE

FOG LAMP
R MR 508190
L MR 508189
R MR 537966
L MR 537965
12PCS 3.03CFT



H3

214-1425

SIDE LAMP
R MB 821172
100PCS CFT



214-1938-2ADCR

BLACK

TAIL LAMP
R
L
10PCS 6.01CFT



214-1971-6

TAIL LAMP
R
L MR 508201
PCS CFT



W21W/W21W/21/5W

TBA

214-1405P-X1

SIDE LAMP
50PRS 0.92CFT



214-1938-1NA

TAIL LAMP
R
L
10PCS 6.01CFT



214-1971-9

TAIL LAMP
R MR 508504
L
PCS CFT



W21W/W21W/21/5W

TBA

214-1946-UE

TAIL LAMP
R MR 124964
L MR 124963
20PCS 2.12CFT



P21W/P21/5W

214-1938-1AD

CHROMED

TAIL LAMP
R MR 376354
L MR 376353
10PCS 6.01CFT



214-1317-UE

BACK LAMP
R MN133776
L MN133775
PCS CFT



W21/5W/PY21W

TBA

MITSUBISHI